



DEPARTMENT OF CIVIL ENGINEERING
GOVT. ENGINEERING COLLEGE, THRISSUR – 9

Ph: 0487-2322989

25.09.2023

STRUCTURAL STABILITY REPORT OF EXISTING BUILDINGS AT KOLATTUR
(MARKKAZUTHASTHIYATHIL IRSHADIYA, MOORKKANAD PANCHAYATH,
MOORKKANAD VILLAGE, MANKADA BLOCK, WARD NO. 2, SURVEY NOS.
306/10-100, 306/10-38, 306/10-39, 306/10-95, 306/10-98, 306/10-99, 306/22
BUILDING NOS. 2/445, 2/443, 2/444) MALAPPURAM DISTRICT

As Per the request letter from The Manager, Markkazuthasthiyathil Irshadiya, Kolattur, I have visited the School building site. I have inspected Three buildings. All of them are of (G+2) Floors. It is found that the structural members such as columns are found intact. Some non-structural cracks were observed on the walls. No cracks were seen on these structural members. Upon Non-destructive (Rebound hammer) testing, the structural concrete is having designed strength. From the inspection & NDT testing, the building is found to be safe for Expected Dead loads & Live loads under Normal Weather Conditions.

However the following points are noted in connection with the above.

1. Need of safety certificate from fire department is not checked.
2. The other construction quality aspects, especially construction joints, construction of walls etc. are not checked in this investigation
3. In future, any new crack found in the structure, the same should be consulted to a structural engineer and the necessary measures should be taken.
4. The Confirmation for KMBR/KPBR of the Building has not been verified



P P Sivan

Assistant Professor in Civil Engineering
Government Engineering College Thrissur

P P Sivan, M.E (Structures)
Assistant Professor in Civil Engg.
Govt. Engg. College Trichur
Thrissur- 680 009
Mob.9809631256
Email-ppsivan@yahoo.com