

# FITNESS CERTIFICATE

(TO BE FILLED BY THE INSPECTING OFFICER)  
(ASST.ENGINEER)

07/09/SFC/AE/PSN/2026-27

Name of School

: Chinmaya Vidyalaya, Senior Secondary School,  
Pallavoor, Palakkad.

1. Name of Officer

: Haridas.R, Assistant Engineer

2. Location

: Pallavoor, Palakkad

3. Period for which the certificate is issued

: 2026-27

4. Types of buildings

: RCC, Administrative block and middle section

Three floors, higher secondary - single storey blocks 2 No  
(As per Attached plan)

5. Nature of defects,if any

a) Foundation and basement

b) Superstructure

c) Doors and windows

d) Wood work Wrought and put up

e) Roof

f) Flooring

g) Miscellaneous

:

:

:

:

:

:

:

:

Nil

6. Any major defects noticed which will render

The building unsafe in any manner

: No

7. Whether maintenance work have been

Done properly

: Yes

8. Whether the structure is sound for

Conducting classes

: Structurally sound for conducting classes under normal

Weather condition


Note: 1. The stability of the structure should be examined also with reference to location ,altitude, intensity of wind, exposure to flood etc. Any additional observation, if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the school was inspected by me on 26/05/2026 and found fit to conduct classes for the period 30/05-2026-2027 for the reasons stated above with following conditions.

PTO

പാലക്കാട് ജില്ലാ പബ്ലിക് വർക്ക്സ് ഓഫീസർ  
പാലക്കാട് ജില്ലാ പബ്ലിക് വർക്ക്സ് ഓഫീസർ  
പാലക്കാട് ജില്ലാ പബ്ലിക് വർക്ക്സ് ഓഫീസർ

1. This certificate is applicable only to safety related to civil construction. For fire safety and safety of electrical installations, electrical lines/conduits shall be obtained from the concerned departments.
2. Maintenance of the school premises should be done periodically. The inspecting officer is not liable for any unfortunate accidents in the school premises due to lack of security or periodic maintenance.
3. This certificate is only for the structural safety of the classrooms mentioned in this certificate. It does not cover safety in laboratories, kitchens, etc.
4. For any new construction in the school compound, it should be intimated and a permit should be obtained from LSGI. Safety measures such as barricades must be ensured.
5. Internal wiring of the school should be verified by a registered /Approved Electrician before conducting classes
6. This fitness certificate is issued based on circular No: GEDN-M1/188/2025-G.EDN by General Education(M)Department Thiruvananthapuram : 13/05/2026 and Circular No - LSGD/2037/2026-EW3, Chief Engineer, Principal Directorate, LSGD. The head of the institution should follow all the instructions in Circular No M3/347/2019- HEALTH Dated : 09/11/2025 Health & Family Welfare (M) Department, Government of Kerala and copies of necessary NOC/Verification reports, after rectification works in schools if any should hand over to this office.

  
Signature

Place: Pallassana

Date: 29/05/2026

**HARIDAS. R**  
**PEN: 370153**  
**ASSISTANT ENGINEER**  
**LID & EW(LSGD) Section**  
**Pallassana Grama Panchayat**  
**Ph : 9447314056.**



**Principal**  
**Chinnaya Vidyalaya**  
**Pallavur, Palakkad**

Annexure ARevised Checklist for School FitnessSchool Name: Chinmaya Vidyalaya Pallavoor.

School Code : \_\_\_\_\_

School Type (Govt./Aided/Unaided): Un Aided.

| Sl.No. | Item to be verified | Yes | No | Remarks |
|--------|---------------------|-----|----|---------|
|--------|---------------------|-----|----|---------|

|    |                              |                                     |                          |  |
|----|------------------------------|-------------------------------------|--------------------------|--|
| 1. | Building Structurally stable | <input checked="" type="checkbox"/> | <input type="checkbox"/> |  |
|----|------------------------------|-------------------------------------|--------------------------|--|

|    |                                         |                                     |                          |  |
|----|-----------------------------------------|-------------------------------------|--------------------------|--|
| 2. | Existing compound walls safe and intact | <input checked="" type="checkbox"/> | <input type="checkbox"/> |  |
|----|-----------------------------------------|-------------------------------------|--------------------------|--|

|    |                                                  |                                     |                          |  |
|----|--------------------------------------------------|-------------------------------------|--------------------------|--|
| 3. | Premises free of unsafe pits, mounds and slopes. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |  |
|----|--------------------------------------------------|-------------------------------------|--------------------------|--|

|    |                                                                      |                          |                          |                     |
|----|----------------------------------------------------------------------|--------------------------|--------------------------|---------------------|
| 4. | Whether the new Constructions comply with Building Rules & approvals | <input type="checkbox"/> | <input type="checkbox"/> | No new construction |
|----|----------------------------------------------------------------------|--------------------------|--------------------------|---------------------|

|    |                                                           |                                     |                          |  |
|----|-----------------------------------------------------------|-------------------------------------|--------------------------|--|
| 5. | Dangerous/ overgrown trees and branches pruned or removed | <input checked="" type="checkbox"/> | <input type="checkbox"/> |  |
|----|-----------------------------------------------------------|-------------------------------------|--------------------------|--|

|    |                                        |                                     |                          |  |
|----|----------------------------------------|-------------------------------------|--------------------------|--|
| 6. | Kitchen does not have any safety issue | <input checked="" type="checkbox"/> | <input type="checkbox"/> |  |
|----|----------------------------------------|-------------------------------------|--------------------------|--|

|    |                                                                 |                                     |                          |  |
|----|-----------------------------------------------------------------|-------------------------------------|--------------------------|--|
| 7. | Whether Asbestos/Tin/ Aluminium sheet roofs have been replaced? | <input checked="" type="checkbox"/> | <input type="checkbox"/> |  |
|----|-----------------------------------------------------------------|-------------------------------------|--------------------------|--|

|    |                                                                            |                                     |                          |  |
|----|----------------------------------------------------------------------------|-------------------------------------|--------------------------|--|
| 8. | Whether Parapet Walls are there for for wells and open wells are covered ? | <input checked="" type="checkbox"/> | <input type="checkbox"/> |  |
|----|----------------------------------------------------------------------------|-------------------------------------|--------------------------|--|

|    |                                                      |                          |                          |    |
|----|------------------------------------------------------|--------------------------|--------------------------|----|
| 9. | Electrical wiring safe (old/damaged wiring replaced) | <input type="checkbox"/> | <input type="checkbox"/> | NA |
|----|------------------------------------------------------|--------------------------|--------------------------|----|

10. Transformers (if nearby) fenced properly

☐
☐

11. No exposed or hazardous electric posts/ electric wires near school.

☐
☐

12. Fire extinguisher installed

☒
☐

Report from KSEB

The inspecting officer may offer remarks regarding item 10 and 11. The head of institution shall rectify the defects and obtain NOC from KSEB in cases pertaining to Items 10 and 11.

#### HEALTH AND SANITATION

13. Adequate, clean, ventilated toilets with running water

☒
☐

14. Classrooms, common areas and kitchen are clean

☒
☐

15. First aid kit available

☒
☐

16. Overgrown vegetation/garbage removed from School premises

☒
☐

17. Rodent control measures are in place

☒
☐

*Haridas R*  
**HARIDAS. R**  
 PEN: 370153  
 ASSISTANT ENGINEER  
 LID & EW(LSGD) Section  
 Pallassana Grama Panchayat  
 Ph : 9447314006.

Items 13 to 17 are to be certified by the Health staff (HI/HS) of the concerned Local Body.

Signature & Seal of School Principal/HM:

Signature & Seal of Health inspector :

Signature & Seal of Assistant Engineer, LSGD:

Inspection Date: 26/5/2026

*Haridas R*  
**HARIDAS. R**  
 PEN: 370153  
 ASSISTANT ENGINEER  
 LID & EW(LSGD) Section  
 Pallassana Grama Panchayat  
 Ph : 9447314006.

*Health Inspector*  
**HEALTH INSPECTOR**  
**F.H.C. PALLASSANA**