

## TO BE FILLED BY THE INSPECTING OFFICER

- 1 Name of School : Chinmaya Vidhyalaya, Kollengode Sub Dist, Palakkad  
2 Name of Officer : SUDHA.S  
3 Location : Kollengode  
4 Period for which Certificate is issued : 2025-2026  
5 Types of building :-

RCC Roofed Building

### Provisional Fitness Mentioned Below

- : 44.70 m x 8.63 m x 12.45 m - 1 Class Room GF, FF, SF  
: 8.58 m x 9.72 x 12.45 m - 1 Class Room  
: 6.48 m x 1.45 m x 12.45 m - 1 Stair Room  
: 6.75 m x 6.92 m x 12.45 m - 1 Stair room  
: 6.70 m x 8.10 m x 7.00 m - 1 Computer Lab GF, FF

### Unfit Building Data given below

- : 22.40 m x 8.10 m x 7.00 m - 1 Office Building  
: 6.75 m x 8.80 m x 7.00 m - 1 Canteen Building  
: 19.95 m x 8.60 m x 7.00 m - 1 Mission Building

- 6 Name of defect if any : Nil  
(a) Foundation and basement : Nil  
(b) Superstructure : Cracks on Wall  
(c) : Nil  
(d) Wood work wrought and put up : Nil  
(e) Roof : Nil  
(f) Flooring : Nil  
(g) Miscellaneous : Nil

Any other major defect noticed

- 7 which will render the building unsafe if any manner : Nil

- 8 Whether maintenance work have been done properly : Yes

- 9 Whether structure is sound for conducting classes : Yes, Structure is sound for conducting classes under normal weather conditions


*Note (i) The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.*

*Note (2) Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.*

Certified that the school was inspected by me on 02-06-2025 and found fit to conduct classes for the period 2025-26 Academic year under normal weather conditions for the reason stated above

Place : Kollengode

Date : 02/06/2025



Signature: *Sudha.S*

Designation: *2/6/2025*

**SUDHA. S**  
PEN.No: 667472  
ASSISTANT ENGINEER  
Local Self Government Department  
Kollengode Gramapanchayat

*04/06/25*