

**TO BE FILLED BY THE INSPECTING OFFICER
(ASSISTANT ENGINEER)**

- 1 Name of Officer : Bindu K C
- 2 Name of School : AL AQSA PUBLIC SCHOOL
- 3 Location with Name of Educational District, Sub District : Kathikode
Irinjalakuda Educational District
Kodungallur Sub District
- 4 Classification buildings as specified in Col.4 of the application for Fitness Certificate & size : Permanent, Multi Storeyed Building
6.10x6.10x3.62m - 13 Class rooms (GF)
6.10x6.10x3.66m - 13 Class rooms (FF)
6.10x6.10x3.63m - 13 Class rooms (SF)
- 5 Period for which the certificate issued : 01.06.2026 to 31.03.2027
- 6 Nature of defect if any
- a) Foundation & basement : No
- b) Superstructure : No
- c) Doors and window : No
- d) Wood work wrought & put up : No
- e) Roof : No
- f) Flooring : No
- g) Miscellaneous (Cracks etc) : No
- 7 Any major defects noticed which will render the building unsafe : No other defects
- 8 Whether maintenance works have been done properly : Yes
- 9 Whether the structure is sound or not for : Sound for conducting classes under normal

Note: 1. The stability of the structure should be examined also with reference to location, attitude, intensity of wind, exposure to flood etc.

2. Any additional observations if indeed necessary for the certificate may be furnished separately with the certificate

Certified that the School was inspected by me on 26.05.2026 and found to be fit to conduct classes for the period from 01.06.2026 to 31.03.2027 for the reason stated above.

Place : Mathilakam

Date : 30.05.2026



Signature:

A handwritten signature in green ink, appearing to be "Bindu K C", with the date "30/5/26" written below it.

Designation:

Assistant Engineer
LSGD Section
Mathilakam Grama Panchayat

Revised Checklist for School Fitness

School Name : AL AQSA PUBLIC SCHOOL


School Code :

School Type (Govt./Aided/Unaided) : Aided

Item To be verified	Yes/No	Remarks
1. Building structurally stable (no cracks, tilting, unsafe walls)	_ Yes	
2. Compound wall intact and safe	_ Yes	
3. Premises free of pits, mounds, unsafe slope	_ Yes	
4. New constructions comply with Building Rules & approvals	_ NA ,	No new construction
5. Dangerous/ overgrown trees pruned or removed	_ Yes	
6. Kitchen does not have any safety issue	_ Yes	
7. Whether Asbestos/Tin/ Aluminium sheet roofs have been replaced?	_ NA	RCC Roof
8. Whether Parapet Walls are there for wells and open wells are covered ?	_ Yes	
9. Electrical wiring safe (old/damaged wiring replaced)	-	The head of institution shall ensure the safety of all electrical Circuits, wiring and electrical installations through an authorised electrical person or the concerned department including fire safty measures through the competent authority with in one month as directed by The Principal Director LSGD
10. Transformers (if nearby) fenced properly	-	The head of institution shall rectify the defects and obtain NOC from KSEB with in one month
11. No exposed or hazardous electric posts/ electric wires near school.	-	The head of institution shall rectify the defects and obtain NOC from KSEB with in one month
12. Fire extinguisher installed	_ Yes	The head of institution shall rectify the defects and obtain NOC from Fire Department

Inspection Date: 26.05.2026

Signature & Seal of the Concerned Department Officer:



[Handwritten Signature]
30/5/26

Assistant Engineer
LSGD Section
Mathilakam Grama Panchayat