

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION

CERTIFICATE

No: 3/2023

Date: 17.6.23


It is certified that an inspection team headed by (Name of Officers with designation) from Raveendran M. Health Inspector FHE Kunthimangala (Name of Department /Office) inspected the Alphonsa Central School, Edat Payyanur, Kannur (Name and Address of the school) on 17.6.23 and found that the Alphonsa Central School, Edat, Payyanur (Name of the school) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/ State/U.T Govt.

The above valid for a period of one year

Signature with Seal :

Name:

Designation :



**HEALTH INSPECTOR
FAMILY HEALTH CENTRE
KUNTHIMANGALAM - KANNUR (DIST.)
04972 612333**

To

Principal
Alphonsa Central School
Edat

J. Anaba Thomas

**MANAGER
ALPHONSA CENTRAL SCHOOL
EDAT, PAYYANUR, KANNUR
Pin: 670 327
AFFL No. 930892**

Shanti
**PRINCIPAL
ALPHONSA CENTRAL SCHOOL
EDAT, PAYYANUR-670 327
SCHOOL CODE: 75862
AFFL No. 930892**