

FITNESS CERTIFICATE

To be filled by the Inspeting Officer (Assistant Engineer/Assistant Executive Engineer)
Re.G.O(Ms)20/70/PWD Dtd.23.01.1970

- 1 Name of Officer : Santo George
- 2 Name of School : Archangels School,Kannikkalam
- 3 Location with Name of Education : Cherupuzha G P
Institution/Sub Dist
- 4 Period for which the certificate is issued : 01.06.2023-31.05.2024
- 5 Classification of Building as specified : Permanent
in column 4 of the application for
fitness certificate and size
- 1) 1x12.45x6.70x3.70
2) 1x12.45x6.70x3.70
3) 1x6.10x6.70x3.70
4) 4x6.10x6.70x3.70
5) 2x6.10x6.70x3.70
6) 1x6.10x6.70x3.70
7) 1x6.10x6.70x3.70
8) 1x44.80x6.70x3.70
9) 4x6.10x6.70x3.70
10) 7x6.10x6.70x3.70
11) 1x12.45x6.70x3.70
- 6 Nature of Defects,if any
- a) Foundation and Basement
- b) Superstructure
- c) Doors and windows Nil
- d) Woodworkwrought and putup
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks etc.)
- 7 Any major defect noticed which will render the building unsafe in any manner None
- 8 Whether maintenance works have been done properly Yes
- 9 Whether the structure is sound or not for conducting classes : The structure is sound for conducting classes under normal wind and weather conditions

Note 1 The stability of the structure should be examined also with reference to location,altitude,intensity of wind ,exposure of flood etc.


2 Any additional observations if deemed necessary for the certificate may be furnished seperately with this certificate

CERTIFICATE

Certified that the school building was inspected by me on 31.05.2023 and is found to be fit to conduct classes for the academic year 2023-24

Place
Date

Cherupuzha
31.05.2023



Assistant Engineer

Assistant Engineer
L I O & E W Section
Cherupuzha Grama Panchayath
email: aelsgdopzpt@gmail.com