## FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer) (Re:G.O. Ms.20/70/PWD Dt.23-01-1970)

| 1 | Name of the Officer  | Jisha M V                                 |
|---|--|---|
| 2 |  | Diamethics vides Bayan's School           |
|   | Name of the School   | Bharathiya vidya Bavan's School           |
| 3 | Location With Name of Education District/Sub.District. Classification of Buildings as specified in Column 4 of the Application for Fitness Certificate and size. | Valiyakunnu ,Kuttippuram, Tirur           |
|   |  | RCC Roof                                  |
| 4 |  |   |
|   |  | 1. 8.60 x 6.10 x 3.70m - 5 nos - GF       |
|   |  | 2. 8.60 x 6.10 x 3.70m - 5 nos - FF       |
|   |  | 3. 6.50 X 6.00 X 3.70M - 4 NOS - GF       |
| 5 | Period for Which the Certificate is Issued   | 2025-2026                                 |
| 6 | Nature of defects, if any  | Nil                                       |
|   | a) Foundation and basement   | Nil                                       |
|   | b)Superstructure<br>c)Doors and windows  | Nil                                       |
|   | d)Wood work wrought and put up   | Nil                                       |
|   | e)Roof   | Nil                                       |
|   | f)Flooring   | Nil                                       |
|   | g)Miscellaneous (Cracks,etc)   | Nil                                       |
|   | Any Major defects noticed which will render the Building   |   |
| 7 | unsafe in any manner   | Nil                                       |
| 0 | La base dono properly  | Yes                                       |
| 8 | Whether maintanance works have been done properly  | Yes, sound and fit for conducting classes |
| 9 | Whether the Structure is sound for conducting classes  | under normal wind and weather             |
|   |  | condition.                                |
|   | Note:1.The stability of the structure should be examined of  | also with reference to                    |

**Note**:1.The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the Certificate may be furnished seperately with this Certificate.

## CERTIFICATE

Certified that the School building was inspected by me on <u>01/07/2025</u> and found to be FIT to conduct classes, for the period 2025-26 for the reasons stated above.

Place: Irimbiliyam Date:03/07/2025

ASSISTANT ENGINEER
LSGD SECTION
IRIMBILIYAM GRAMA PANCHAYAT
P.O. VALIYAKUNNU, Pin: 676 557