

APPENDIX-XI

BUILDING SAFETY CERTIFICATE

No.: 9&22


Date: 99/3/24

Certified that the existing building Carmel Academy School at Durgapur Open Cast Road, Chandrapur comprised of G+3 owned by Carmel Academy School, Tukum, Chandaur have complied with the Building Safety requirement in accordance with National Building code Rules, and verified by Shri A.W. Khan, Govt. Registered Structural & Chartered Engineer, Chandrapur & the Engineers of P.W.D. Sub-Division No.1 also visited the said site on Dt. 07/03/2024 in presence of Fr. Jaison (Principal) and that the building is fit for occupancy upto classes XII with effect from 2023-2024 for a period of 3 (THREE) years in accordance with rule and subject to compliance of the specific condition as appended.

- 1) Structural Stability should be examined also with reference to location, altitude, intensity of wind floor.
- 2) Fire safety inspection / report should be done by agency separately.

Issued on 11-03-2024 at Chandrapur by

* Strike out whichever is not applicable.


Sub Divisional Engineer
Public Works Sub Division No.1
Chandrapur

Signature with Seal



Name : MR. SUNIL KUMBHE


Executive Engineer
Designation: Public Works Sub Division No.1
Chandrapur

Name & Address of Department / Office: Public Works
Division No.1
Chandrapur.

Note: This certificate should be signed/ issued by Assistant Engineer & above officer of concerned Govt. Department only.

The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English is uploaded along with the original vernacular certificate as a single pdf.


MANAGER
BJM Carmel Academy, Tukum
Chandrapur


Principal
BJM Carmel Academy
DOC Road, Tukum,
Chandrapur-442 401