

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

JYOTHIRAJ P.S.

Blooming Buds Bethania English School
Vellithiruthy / Chavakkad / Kannamkulam

5. Period for which the certificate is issued
6. Nature of defects, if any

a) Foundation and basement

b) Superstructure

c) Doors and Windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks, etc.)

7. Any major defects noticed which will render the building unsafe in any manner

Nil

- No

8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

Please see the revised checklist for school fitness (Annexure A) attached with this.

Yes

Sound under normal wind and weather conditions

CERTIFICATE

certified that the school building was inspected by me on 25/07/2026 and found to be fit / unfit to conduct classes, for the period 2026-27 Academic year for the reasons stated above.

Place : Chavakkad

Date : 25/07/2026

500/8-6-13



MANAGER

BLOOMING BUDS BETHANIA ENGLISH SCHOOL
SENIOR SECONDARY
VELLITHIRUTHY, MARATHAMCODE-680604
CBSE AFF.NO : 930307



PRINCIPAL
BLOOMING BUDS BETHANIA ENGLISH SCHOOL
SENIOR SECONDARY
VELLITHIRUTHY, MARATHAMCODE-680604
CBSE AFF.No: 930307

JYOTHIRAJ P.S.

PEN: 588421

ASSISTANT ENGINEER
LSCD (LID & EW) SECTION
THRASSUR DT