

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 119

Dated: 07.02.2025

It is certified that the existing building CARMEL ACADEMY AMGAON, WADSA (name of the building or premises) at Amgaon, Tal. Desaiganj, Dist. Gadchiroli (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + 2	Nil	Nil	Nil	Nil	Nil

The building is owned/occupied by CARMEL ACADEMY AMGAON, WADSA (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Z.P. Works Sub-Division Wadsa (Name of Department/ Govt.) on 06.02.2025 (date of inspection) in the presence of Jose Augustine (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 07.02.2025 for a period of one (01) years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 07.02.2025 at Desaiganj by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal

Junior Engineer

Z.P. (W) Sub-Div. Wadsa  
Name: Nabir R. Fule

Designation: Junior Engineer

Name & Address of Department/ Office: Zilla

panished works sub division  
Desaiganj