

# Annexure D

## BUILDING SAFETY CERTIFICATE

No.

Dated: 20.04.26

It is certified that the existing building Carmel Academy, Amgaon (name of the building or premises) at Amgaon, Taluka - Wadsa, Dist. Gadchiroli (address) is having block(s)/Floor(s) as per details below:

| Detail of Block(s) in school | Block (1)        | Block (2) | Block (3) | Block (4) | Block (5) | Block (6) |
|------------------------------|------------------|-----------|-----------|-----------|-----------|-----------|
| No. of Floor(s) in the Block | Ground<br>↓<br>1 |           |           |           |           |           |


The building is owned/occupied by Carmel Academy, Amgaon, wadsa (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D. (Name of Department/ Govt.) on 20.04.26 (date of inspection) in the presence of Jose Augustine, Amgaon (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 20.04.26 for a period of 01 (one) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Structural stability should be examined also with reference to location, attitude, intensity of wind flood.
2. Fire safety inspection, Report should be done by agency separately.
3. Electrical safety inspection should be done by agency separately.

Issued on 20.04.26 at Wadsa by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

  
Sub-Divisional Engineer  
P.W.Sub-Dn., Wadsa

Signature with Seal :   
Name : (A.R. MORE)  
Designation : Executive Engineer  
Public Works Division No 1  
GADCHIROLI

Name & Address of Department/ Office



कार्यालय,कार्यकारी अभियंता,  
सार्वजनिक बांधकाम विभाग क्र.१,  
गडचिरोली.

|                                   |                                     |
|-----------------------------------|-------------------------------------|
| दुरध्वनी व फॅक्स क्र.०७१३२/२३३४१५ | E-mail :- gadchirol1.ee@mahapwd.com |
| जा.क्र. १२४३ /तां./का-२ (५) /२०२६ | दिनांक :- २७/०४/२०२६                |

प्रति,

प्राचार्य,  
कॉरमेल अकाडमी, आमगांव,  
ता.देसाईगंज, जि.गडचिरोली.

विषय :- इमारत सुरक्षा व शैक्षणिक कामाकरीता योग्यता प्रमाणपत्र मिळणेबाबत.

- संदर्भ :- १. आपले पत्र क्र. सीएए/बीएससी/२८७, दिनांक १६/०२/२०२६.  
२. उपविभागीय अभियंता, सा.बां.उपविभाग, वडसा यांचे पत्र क्र. ३२८/२०२६, दिनांक २१/०४/२०२६.

उपरोक्त संदर्भिय पत्रान्वये मागविलेले विषयांकित प्रमाणपत्र सोबत सादर करण्यात येत आहे.

सहपत्र :- इमारत सुरक्षा प्रमाणपत्र.



(ए.अर.मोरे)  
कार्यकारी अभियंता  
सार्वजनिक बांधकाम विभाग क्र.१,  
गडचिरोली.