

# FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

No. 10/EC/AE/LID&EW/TVNR/25-26

1. Name of the Officer ..... ASHNA R.
  2. Name of the School ..... Hilltop Public School Maravanchery
  3. Location with name of Education District/ Sub. District ..... Thavanur Tivur Edu Dist
  4. Classification of Building as specified in column 4 of the application for fitness certificate and size.  
..... RCC Building (G+2)  
..... 6.10 x 6.15 x 3.70 m  
..... 12.40 x 6.15 x 3.70 m  
..... 12.85 x 6.15 x 3.70 m  
..... 6.45 x 6.10 x 3.70 m  
..... 6.85 x 6.10 x 3.70 m  
..... 18.70 x 6.10 x 3.70 m
  5. Period for which the certificate is issued ..... 2025-2026.
  6. Nature of defects , if any  
a) Foundation and basement .....  
b) Superstructure .....  
c) Doors and Windows .....  
d) Wood work wrought and put up ..... N/I  
e) Roof .....  
f) Flooring .....  
g) Miscellaneous (Cracks, etc.) .....  
7. Any major defects noticed which will render the building unsafe in any manner ..... N/I
  8. Whether maintenance works have been done properly ..... Yes
  9. Whether the structure is sound or not for conducting classes ..... Sound under normal wind and weather conditions.
- Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on ..... 28/05/2025 ..... and found to be  fit /  unfit to conduct classes, for the period ..... 2025-2026 ..... for the reasons stated above.

Place : Thavanur

Date : 29/05/2025



Assistant Engineer  
ASSISTANT ENGINEER  
LID & EW SECTION  
THAVANUR GRAMA PANCHAYATH  
PIN: 679 573