

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1 Name of the Officer

Assistant Engineer, LID&EW Section, Bisonvalley grama panchayath

2 Name of the School

Holy Family Public School Kunchithanny

3 Location with name of Education District/  
Sub. District

Thodupuzha

4 Classification of Building as specified in column 4 of the application for fitness certificate and size

|    | L         | B        | H     | No. of Class rooms | Remark       |
|----|-----------|----------|-------|--------------------|--------------|
| 1  | 43.4 m X  | 6.75 m X | 3 m   | 6                  | Cellar       |
| 2  | 50.1 m X  | 5.5 m X  | 3.7 m | 8                  | Ground Floor |
| 3  | 10.95 m X | 4 m X    | 3.7 m |                    | Ground Floor |
| 4  | 6.45 m X  | 1.95 m X | 3.7 m |                    | Ground Floor |
| 5  | 5 m X     | 4.7 m X  | 3.7 m |                    | Porch        |
| 6  | 50.1 m X  | 5.5 m X  | 3.7 m | 7                  | First Floor  |
| 7  | 10.95 m X | 4 m X    | 3.7 m |                    | First Floor  |
| 8  | 6.45 m X  | 1.95 m X | 3.7 m |                    | First Floor  |
| 9  | 5 m X     | 4.7 m X  | 3.7 m |                    | First Floor  |
| 10 | 10.9 m X  | 6.05 m X | 3.7 m |                    | Second Floor |
| 11 | 11 m X    | 3.55 m X | 3.7 m |                    | Second Floor |
| 12 | 5 m X     | 4.7 m X  | 3.7 m |                    | Second Floor |
| 13 | 9.25 m X  | 8.9 m X  | 3.7 m |                    | GI Sheet     |

5 Period for which the certificate is issued

2025-26

6 Nature of defects, if any

Nil

a) Foundation and basement

b) Superstructure

c) Doors and Windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks, etc.)

7 Any major defects noticed which will render the building unsafe in any manner

NA

8 Whether maintenance works have been done properly

Yes

9 Whether the structure is sound or not for conducting classes

Sound

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate


## CERTIFICATE

Certified that the school building was inspected by me on 13/06/2025 and found to be fit / ~~unfit~~ to conduct classes, for the period 2025-26 for the reasons stated above

Place : Pottankad

Date : 16-06-2025

(Seal)



*Anelsha A.Y.*  
Assistant Engineer  
LID & EW Section, Bisonvalley  
PEN : 090591