

FITNESS CERTIFICATE

- 1 Name of officer : SHYLAJA.K.P
- 2 Name of school : Malikdeenar public school, Adivad
- 3 Location with Education District/Subdistrict : adivadu,Kothamangalam
- 4 Classification of Building as specified in column 4 of the application of fitness certificate and size : Permanent Building
Ground floor area 845.84m2
class room 8x5.5x7.5x3.6 M
office room 1x5.83x10.05x3.6 M
principal room 1x4.0x7.5x3.6 M
First floor area 845.84m2
class room 7x5.5x7.5x3.6 M
" 1x5.5x10.5x3.6 M
Library 1x9.73x7.5x3.6 M
Second floor area 816.27m2
class room 6x5.5x7.5x3.6 M
" 1x 9.8x9.32x3.6 M
" 1x5.5x10.5x3.6 M
staff room 1x5.5x9.32x3.6 M
- 5 Period for which the certificate is issued : 2026-27
- 6 Nature and defects if any :
a)Foundation and Basement : Nil
b)Super structure : Nil
c)Doors and windows : Nil
d)Woodwork wrought and put up : Nil
e)Roof : Nil
f)Flooring : Nil
g)Miscellaneous(cracks etc) : Nil
- 7 Any major defects noticed which will render the building unsafe in any manner : Nil
- 8 Whether maintenance works have been done properly : Yes
- 9 Whether the structure is sound or not for conducting classes : Yes, Structure is sound for conducting classes under normal wind and weather condition

CERTIFICATE

Certified that the school building was inspected by me on 31/8/2026 and found to be fit to conduct classes ,for the period 2026-27for the reasons stated above.

Kothamangalam
31/08/2026



Assistant Executive Engineer

SHYLAJA K.P.(PEN: 611225)
Assistant Executive Engineer
LID & EW Sub Division
Kothamangalam Block Panchayat