

## STRUCTURAL STABILITY CERTIFICATE

Name of the School : Model public school, Technocity west,  
Pallipuram,

Village, Town, District

In which the school is situated : Survey No. 376/12, 376/14-1, Pallipuram  
Village, Thiruvananthapuram

The area on which the classes

Are running : 3566.4 Sqm

Building Nos From Panchayath/

Authority : Andorkonam Grama panchayath  
1/428, 1/129

I certify that I have inspected the school building on 15/03/2021 referred to the above and examined the various parts including foundation, columns, beams etc. I am of the opinion that the buildings are structurally sound and their stability will not be endangered by their use as School.

Vahutharaud,

23/03/2021

DINESH .K, ME structural

Reg No: 081038129006 / 2010

Anna University Coimbatore

**FITNESS CERTIFICATE OF SCHOOL BUILDINGS**  
**TO BE FILLED BY THE INSPECTING OFFICER**  
**(ASSISTANT ENGINEER)**

**Name of School: Model Public School,CRPF,Pallippuram.**

- 1 Name of the Officer : Shibu M.S,Assistant Engineer,  
LSGD Section, Andoorkonam GP
- 2 Location : CRPF,Pallippuram
- 3 Period for which the certificate is issued : 2022-2027

4 Types of building(dimensions are in meters)

|            |                                 |     |
|------------|---------------------------------|-----|
| Building 1 | Three Storeyed - 43.84m x 6.96m | RCC |
| Building 2 | Two storeyed - 50.40m x 16.70m  | RCC |
| Building 3 | Two storeyed - 21.90 m x 9.75m  | RCC |

- 5 Nature of defect if any : Nil
- a Foundation and basement : Nil
- b Superstructure : Nil
- c Doors and windows : Nil
- d Wood work wrought and put up : Nil
- e Roof : Nil
- f Flooring : Nil
- g Miscellaneous(cracks if any) : Nil
- 6 Any major defects noticed which will render the building unsafe in any manner : No
- 7 Whether maintainance works have been done properly : Yes
- 8 Whether the structure is sound or not for conducting the classes : Yes,Sound to conduct classes under normal wind and weather conditions.

Note:-

- 1 The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc
- 2 Any additional information deemed necessary for the certificate ,may be furnished separately with the certificate.

Certified that the school was inspected by me on ...23-05-2022....and found to be fit to conduct classes for the period for the reasons stated above.

Place:Andoorkonam

Date : 24/05/2022

Signature:

Designation:



Assistant Engineer  
LSGD Section  
Andoorkonam Grama Panchayat

