FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Exe .Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer — ANNAMMA BENNY MANGATTUSSERI
2. Name of the School — NGPM CENTRAL SCHOOL, VENCHAM
3. Location with name of Education District/ Sub. District — VENCHEMPU, PUNALUR DIST. ANCHAL SUB DIST
4. Classification of Building as specified in column 4 of the application for fitness certificate and size. — 1) R.C.C BUILDING
   G.F - 59.5m x 8.95m x 3.70m
   F.F - 59.5m x 8.95m x 3.70m
   S.F - 59.5m x 8.95m x 3.70m
   2) SHEET (SANDWICH) ROOF BLDG
   G.F - 90.0m x 7.50m x 3.70m
5. Period for which the certificate is issued — JUNE 2023 - MARCH 2024
6. Nature of defects , if any
   a) Foundation and basement
   b) Superstructure
   c) Doors and Windows — NIL
   d) Wood work wrought and put up
   e) Roof
   f) Flooring
   g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner — NIL
8. Whether maintenance works have been done properly — YES
9. Whether the structure is sound or not for conducting classes — YES

Note : *1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.*

CERTIFICATE

certified that the school building was inspected by me on 25-05-2023 and found to be fit / ~~unfit~~ to conduct classes, for the period JUNE 2023 - MARCH 2024 for the reasons stated above.

MANANGER
N.G.P.M. CENTRAL SCHO
VENCHEMPU PUNALU

Place KARAVALOOR

Date 25-05-2023

Self attested

(Seal)

PRINCIPAL
N.G.P.M CENTRAL SCHOOL
VENCHEMPU, PUNALUR

N.G.P.M. CENTRAL SCHOOL VENCHEMPU PUNALUR

ASSISTANT ENGINEER
LID & EW SECTION
KARAVALOOR GRAMA PANCHAYAT