

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- |   |   |
|---|---|
| 1. Name of the Officer  | P V ANANDAN   |
| 2. Name of the School   | Notre Dame School Vettikuzhi, Chaipenkuzhy  |
| 3. Location with name of Education District/ Sub. District  | Thrissur/Chalaky  |
| 4. Classification of Building as specified in column 4 of the application for fitness certificate and size. | Permanent Multi-Storied Building (GF+FF)(New Block)<br>GF= 8 Class rooms of 6.00x6.80x3.75m<br>1 Class room of 12.00x6.80x3.75m<br>FF= 4 Class rooms of 6.00x6.80x3.75m<br>1 Class room of 12.00x6.80x3.75m |
| 5. Period for which the certificate is issued   | Upto 31-March-2025  |
| 6. Nature of defects , if any   |   |
| a) Foundation and basement  | NIL   |
| b) Superstructure   | NIL   |
| c) Doors and Windows  | NIL   |
| d) Wood work wrought and put up   | NIL   |
| e) Roof   | NIL   |
| f) Flooring   | NIL   |
| g) Miscellaneous (Cracks, etc.)   | NIL   |
| 7. Any major defects noticed which will render the building unsafe in any manner                            | NIL   |
| 8. Whether maintenance works have been done properly  | YES   |
| 9. Whether the structure is sound or not for conducting classes   | physically is sound under normal wind and weather conditions  |
- Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

Certified that the school building was inspected by me on 11/08/2025 and found to be fit / unfit to conduct classes, for the period 31-March-2026 but the classes should not be held in a building that does not generate fitness and is unsafe for the reasons stated above.

Place: Vettilappara  
Date: 11/08/2025



SQ/PA-6-12

Assistant Engineer  
L.B.O. (E) SECTION  
THRASSUR-68 721

Fitness Certificate issued as per the above conditions on 11/8/25.

Assistant Engineer  
L.B.O. (E) SECTION  
ATRAPPALLY  
THRASSUR-68 721