

FITNESS CERTIFICATE OF SCHOOL BUILDINGS

TO BE FILLED BY THE INSPECTING OFFICER

(ASSISTANT ENGINEER)

Name of School: Peace international school

1 Name of the Officer

Deepthi E.K, Assistant Engineer,

: LSGD Section, Kuruvattur

2 Location

: Cheruvatta

3 Period for which the certificate is issued

: 2023-24

4 Types of building (dimensions are in meters)

Three storied Permanent RCC Building

Block 1	
GF	Class room 5 no (6.00 x 7.50) Principal Room 1 no (6.00 x 4.20)
FF	Class room 6 no (6.00 x 7.50)
Block 2	
Basement floor	Two storied RCC Building Class room 5 no (6.00 x 7.50)
GF	Class room 5 no (6.00 x 7.50)

5 Nature of defect if any

: Nil

a Foundation and basement

: Nil

b Superstructure

: Nil

c Doors and windows

: Nil

d Wood work wrought and put up

: Nil

e Roof

: Nil

f Flooring

: Nil

g Miscellaneous (cracks if any)

: Nil

6 Any major defects noticed which will render the building unsafe in any manner

: No

7 Whether maintenance works have been done properly

: Yes

8 Whether the structure is sound or not for conducting the classes

: Yes, Sound to conduct classes under normal wind and weather conditions.

Note:-

1 The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc

2 Any additional information deemed necessary for the certificate, may be furnished separately with the certificate.

Certified that the school was inspected by me on 18.07.2023 and found to be fit to conduct classes for the period for the reasons stated above.

Place: Kuruvattur

Date: 18.07.2023



PEACE INTERNATIONAL SCHOOL
Manager

Signature:

(Signature)
18/7/23

Designation:

Assistant Engineer
LSGD Section
Kuruvattur

(Signature)
Principal

Peace International School
KOZHIKODE