

FITNESS CERTIFICATE

TO BE FILLED BY THE INSPECTING OFFICER

(ASSISTANT ENGINEER)

- 1 Name of the Officer : ELDO SIMON
- 2 Name of the School : St. Anne's Public School, Anathadam , Manakulangara P.O
- 3 Location with Name of Educational District
Sub District : Chalakudy Sub Dist. Irinjalakuda Dist.
- 4 Classification buildings as specified in Col. 4 : 6.12*6.85*3.60 (29- Class Room, Office Room)
of the application for fitness certificate & Size : 6.12*6.85*3.60 (1- Hall, 4 – Lab ,1- Sports Room)
: 6.90*8.00*3.60 (Staff Room, Library, Prayer room, Office Room)
- 5 Period For which the certificate is issued : 2024-25
- 6 Nature of Defect if any
- cc) Foudation and Basement : Good Condition
- dd) Super Structure : Good Condition
- ee) Doors and Windows : Good Condition
- ff) Wood Work Wrought put up : Nil
- gg) Roof : Good Condition
- hh) Flooring : Good Condition
- ii) Miscellaneous cracks etc : Cracks affecting safety not visible
- 9 Any major defects noticed which will render the building unsafe if any manner : No
- 8 Whether the maintenance works have been done properly : Yes *fit*
- 9 Whether structure is safe for conducting classes : Sound under normal weather conditions.


NB: Stair Room to be locked

CERTIFICATE

Certified that the school building was inspected by me on **21-05-2024** and found to be fit/~~unfit~~ to conduct classes, for the period **2024-25** for the reasons stated.

Place: Kodakara
Date: 23-05-2024

(Seal)



Assistant Engineer

ELDO SIMON
PEN: 859565
ASSISTANT ENGINEER
LSGD - LID&EW SECTION
KODAKARA