FITNESS CERTIFICATE FOR SCHOOL BUILDING FOR 2025-26

- Name of Officer
- 2, Name of School
- 3, Location with name of Edl. District
- 4, Classification of buildings

: NILEENA RAPHEL

ST. JOSEPH PUBLIC SCHOOL, MANALIMUKKU,

EDATHALA

: ALUVA.

Permanent RCC Three Storied building and Top roof AC

sheet

Specification				Size			
Ground Floor,RCC Roof							
Class room	15	8.00	X	6.00	X	4.20	mtr
Class room	1	6.70	X	6.00	X	4.20	mtr
Class room	1	5.00	X	6.00	X	4.20	mtr
Class room	1	3.90	X	6.00	X	4.20	mtr
Class room	2	15.17	X	6.00	X	4.20	mtr
Class room	1	13.20	X	9.20	X	4.20	mtr
Class room	1	3.90	X	9.20	X	4.20	mtr
Class room	1	3.70	X	6.00	X	4.20	mtr
Class room	1	3.90	X	3.00	X	4.20	mtr
Class room	1	6.00	X	2.40	X	4.20	mtr
First floor,RCC Roof							
Class room	13	8.00	χ	6.00	X	4.20	mtr
Class room	1	15.40	χ	8.00	X	4.20	mtr
Class room	1	16.20	X	6.00	X	4.20	mtr
Class room	3	13.20	X	6.00	X	4.20	mtr
Class room	1	13.20	X	9.20	X	4.20	mtr
Class room	2	15.17	X	6.00	X	4.20	mtr
Class room	1	5.00	X	6.00	X	4.20	mtr

- 5. Period for which the certificate is issued
- 6, Nature of defects if any
 - a) Foundation and basement
 - Superstructure
 - Doors and Windows
 - d) Wood work wrought and putup
 - e) Roof
 - Flooring
 - Miscelleneous (Crack etc.)
- 7, Any major defects noticed which will render the building unsafe in any manner
- 8, Whether maintenance work have been done properly
- 9, Whether the structure is sound or not for conducting classes

GRAMA PANCHAYATH

G.D. SECT

RCC Framed structure with footing

2025-26

Solid Block Masonry in Cement with RCC

Done with MDF frames and shutters with flush doors

Windows with Aluminium frame with closed shutters and iron grills

RCC

Ceramic tiles over the concrete bedding

Nil

Yes

The building structure is Fit for conducting Classes under . normal weather condition

Certified that the school was inspected by me on ... 20 - 0.5 - ... 2025. And found to be EDATHALA GRAMA PANCHAYATH fit to conduct classes for the period upto 31st March 2026 for the reason stated above.