

# FITNESS CERTIFICATE FOR SCHOOL BUILDING FOR 2026-27

1, Name of Officer **NILEENA RAPHEL**  
 2, Name of School **ST. JOSEPH PUBLIC SCHOOL, MANALIMUKKU, EDATHALA**  
 3, Location with name of Edl. District **ALUVA.**  
 4, Classification of buildings **Permanent RCC Three Storied building and Top roof AC sheet**

<u>Specification</u>	<u>Size</u>
<b>Ground Floor,RCC Roof</b>	
Class room	8.00 } 6.00 x 4.20 mtr
Class room	6.70 } 6.00 x 4.20 mtr
Class room	5.00 } 6.00 x 4.20 mtr
Class room	3.90 } 6.00 x 4.20 mtr
Class room	15.17 } 6.00 x 4.20 mtr
Class room	13.20 } 9.20 x 4.20 mtr
Class room	3.90 } 9.20 x 4.20 mtr
Class room	3.70 } 6.00 x 4.20 mtr
Class room	3.90 } 3.00 x 4.20 mtr
Class room	6.00 } 2.40 x 4.20 mtr
<b>First floor,RCC Roof</b>	
Class room	8.00 } 6.00 x 4.20 mtr
Class room	15.40 } 8.00 x 4.20 mtr
Class room	16.20 } 6.00 x 4.20 mtr
Class room	13.20 } 6.00 x 4.20 mtr
Class room	13.20 } 9.20 x 4.20 mtr
Class room	15.17 } 6.00 x 4.20 mtr
Class room	5.00 } 6.00 x 4.20 mtr



5, Period for which the certificate is issued

**2026-27**

6, Nature of defects if any

- |   |  |
|---|--|
| <ul style="list-style-type: none"> <li>a) Foundation and basement</li> <li>b) Superstructure</li> <li>c) Doors and Windows</li> <li>d) Wood work wrought and putup</li> <li>e) Roof</li> <li>f) Flooring</li> <li>g) Miscellaneous ( Crack etc )</li> </ul> | <ul style="list-style-type: none"> <li>RCC Framed structure with footing</li> <li>Solid Block Masonry in Cement with RCC</li> <li>Done with MDF frames and shutters with flush doors</li> <li>Windows with Aluminium frame with closed shutters and iron grills</li> <li>RCC</li> <li>Ceramic tiles over the concrete bedding</li> </ul> |
|---|--|

7, Any major defects noticed which will render the building unsafe in any manner

Nil

8, Whether maintenance work have been done properly

Yes

9, Whether the structure is sound or not for conducting classes

The building structure is Fit for conducting Classes under normal weather condition

Note : (1) The stability of the structure should be examined also with reference to location,altitude,intensity of wind, exposure of flood etc.

(2) Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

(3) This certificate is applicable only for safety related to civil construction.(Separate certificates for fire safety and safety for electrical installations,electrical lanes/conduits shall be obtained from concerned department.

(4) Maintenance of school premises should be done periodically.The inspecting officer is not liable for any unfortunate accidents in the school premises due to lack of security/periodical maintenance.

### CERTIFICATE

Certified that the school was inspected by me on 01-06-2026 And found to be fit to conduct classes for the period upto 31st March 2027 for the reason stated above.



*Nileena*  
NILEENA RAPHEL  
ASSISTANT ENGINEER  
LSGD SECTION  
EDATHALA GRAMA PANCHAYATH