

FITNESS CERTIFICATE

TO BE FILLED BY THE INSPECTING OFFICER
(ASSISTANT ENGINEER)

- 1 Name of the Officer : ANJU KUNJUMON
- 2 Name of the School : ST. LIOBA Academy
- 3 Location with Name of Educational District
- Sub District : Chalakudy Sub Dist. Irinjalakuda Dist.
- 4 Classification buildings as specified in Col. 4 : 7.20 * 6.60 * 3.70 (7-class rooms) GF
- of the application for fitness certificate & Size : 7.20 * 6.60 * 3.70 (7-class rooms) FF
- : 7.20 * 6.60 * 3.70 (4-class rooms) SF
- 5 Period for which the certificate is issued : 2026-27
- 6 Nature of Defect if any
- h) Foundation and Basement : Good Condition
- i) Super Structure : Good Condition
- j) Doors and Windows : Good Condition
- k) Wood Work Wrought put up : Nil. Damaged wood replaced.
- l) Roof : Good Condition
- m) Flooring : Good Condition
- n) Miscellaneous cracks etc : Cracks affecting safety not visible
- 7 Any major defects noticed which will render
- the building unsafe if any manner : No
- 8 Whether the maintenance works have been
- done properly : Yes
- 9 Whether structure is safe for conducting classes : Sound fit under normal wind and weather conditions

CERTIFICATE

Certified that the school building was inspected by me on 22-05-2026 and found to be fit/unfit to conduct classes, for the period 2026-27 for the reasons stated.

Building is structurally stable and clearance from health department is obtained. Hence the structure is deemed fit from this perspective. However vide order NO: GEDN-MI/ISS/2025-GEDN, dated 13.05.2026, H.M should ensure fitness check from Electrical Inspectorate, Fire and Rescue Services Dept, Forest and Wild life dept., and Motor Vehicle Dept. within stipulated period.

Place: Kodakara
Date: 29-05-2026

(Seal)



Assistant Engineer

ASSISTANT ENGINEER
L.S.G.D.
Kodakara Section
Date: