

TO BE FILLED BY THE INSPECTING OFFICER

Name of School :

ST.MARY'S BETHANY SCHOOL

1. Name of Officer : SAJITHA T S, Assistant Engineer,
LID&EW Section, Karimba
GramaPanchayath.
2. Location : Karimba
3. Period for which Certificate is issued : 2025-26
4. Types of building : RCC Framed Structure
- GF – 6.10 x 6.10 x 3.65 -1 Office room
GF – 6.10 x 6.10 x 3.65 - 1 Staff room
GF – 6.10 x 6.10 x 3.65 - 16 Classroom
FF – 6.10 x 6.10 x 3.65 -1 Office room
FF – 6.10 x 6.10 x 3.65 - 1 Staff room
FF – 6.10 x 6.10 x 3.65 – 7 Classroom
FF – 9.10 x 6.10 x 3.65 - 3 Classroom
FF – 9.10 x 6.10 x 3.65 - 2 Lab room
FF – 9.10 x 6.10 x 3.65 – 1 Library
SF – 6.10 x 6.10 x 3.65 - 13 Classroom
SF – 37.80 x 6.10 x 3.65 -1 Hall
39 Classroom + 2 Office room + 2
Staff room + 2 Lab room + 1 Library)

Name of defect if any

:

- (a) Foundation and basement : NIL
- (b) Superstructure : NIL
- (c) Doors and windows : NIL
- (d) Wood work wrought and put up : NIL
- (e) Roof : NIL
- (f) Flooring : NIL
- (g) Miscellaneous : NIL

6. Any other major defect noticed which will

- render the building unsafe in any manner : NIL
7. Whether maintenance work have been done properly : YES
8. Whether structure is sound for conducting classes : YES, Structure is sound for conducting classes under normal wind and weather condition

Note : (1) The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.

(2) Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 06/06/2025 and found fit to conduct classes for the period for the reason stated above.

Note:-

Place: Karimba
Date :06/06/2025

