

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)


1. Name of the Officer SARITHA K.A
2. Name of the School ST. RAPHAEL'S PUBLIC SCHOOL, KALLUR
3. Location with name of Education District/ Sub. District KALLUR, THRISSUR
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.
5. Period for which the certificate is issued 2020-21
6. Nature of defects , if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner NIL
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes structure is sound under normal weather & climate condition.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 19/10/2020 and found to be fit / unfit to conduct classes, for the period 2020-21 for the reasons stated above.

Place : Kallur
Date : 19/10/2020



Saritha K.A.
SARITHA K.A.
Assistant Engineer
L. S. G. D.
Thrikkur Grama Panchayath