

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer DILEEP.L
2. Name of the School ST. THOMAS SCHOOL
3. Location with name of Education District/ Sub. District PUNALUR
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.
MAIN Block. G+2 - 2074m². Ht 12.7m
Lilly Block. G+1 1216m² with 8.42m Ht
5. Period for which the certificate is issued 2026-2027 ACADEMIC YEAR
6. Nature of defects , if any
a) Foundation and basement } NIL
b) Superstructure }
c) Doors and Windows } Nil
d) Wood work wrought and put up }
e) Roof }
f) Flooring }
g) Miscellaneous (Cracks, etc.) }
7. Any major defects noticed which will render the building unsafe in any manner NIL
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes Sound Under Normal weather condition

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 12/05/2026 and found to be fit / unfit to conduct classes, for the period 2026 - 27 for the reasons stated above.

Place: Punalur
Date: 14/05/2026



[Signature]
Assistant Engineer
Punalur Municipality

JACOB THOMAS
SENIOR PRINCIPAL
ST. THOMAS CENTRAL SCHOOL
PUNALUR, KOLLAM, KERALA

JACOB THOMAS (MAJABATHUR)
ST. THOMAS CENTRAL SCHOOL
Punalur, Kollam (Dist), Kerala
Mob: 9447122760