FITNESS CERTIFICATE

To be filled by the inspecting Officer(Asst.Engineer) (Re:GO Ms.20/70/PWD Dt.23-01-1970)

Name of the Officer

: ARAVIND M

Name of the School

: Tagore Public School

3 Location with name of education District/Sub District Classification of Building as specified in column 4 of the : Rajapuram ,Kanhangad

application for fitness certificate and size

GROUND FLOOR	2	(6.00x6.00x3.60)m	RCC Class Room
	1	(10.00x6.00x3.60)m	RCC Office Room
FIREST	4	(6.00x6.00x3.60)m	RCC Class Room
	1	(5.80 x 6.00x3.60)m	RCC Class Room
	1	(4.00 x 6.00x3.60)m	Store Room
SECOND	4	(6.00x6.00x3.60)m	RCC Class Room
	1	(10.00x6.00x3.60)m	Lab
	1	(12.200x6.00x3.60)m	Staff room
THIRD	4	(6.00x6.00x3.60)m	RCC Class Room
	1	(10.00x6.00x3.60)m	Lab Room

. For the academic year 2024-25

Nil

5 Period for which the certificate is issued

6 Nature of defects, if any

Foundation and basement a)

Superstructure p)

doors and Windows C)

Wood-work wrought and put up ď)

Roof

Flooring Miscellaneous(Cracks, etc)

7 Any major defects noticed which will render the

Nil building unsafe in any manner

Yes 8 Whether maintanance works have been done properly

9 Whether the structure is sound or not for conducting classes : The structure is sound for conducting classes under normal weather conditions

1. The stability of the structure should be examined also with reference to location, altitude, intensity

of wind, exposure of flood etc.

P.O. Rangur im

2.Any additional observations if deemed necessary for the certificate may be fumished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 11/04/2024 and found to be fit to conduct classes, for the period 2024-25 for the reasons stated above

Place: Rajapuram Date :11/04/2024

Note:

Seal

Kallar Grama GangkayaANCHAYAT RAJAPURAM-671532

PRINCIPAL (Senior Secondary) (CBSE No: 930382) P.O. Rajapuram-671532 Kasaragod, Kerala

Tagore Public School

(FRANCIS K. MANI)

