

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No.

Dated: 24/02/2024

It is certified that an inspection team headed by Health Inspector Thaluk Hospital Poodamkallu, Kasaragod (Dist), Sreekumar (HI)
(Name of Officers with designation) from

(Name of Department/ Office) inspected the Tagore Public School Rajapuram.

(Name & Address of the school) on 24/02/24 (date of inspection) and found that the Tagore Public School (Name of school) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/ State/ U.T. Govt.

The above is valid for a period of 2024 - 2025



Signature with Seal:

Name

Designation

Name & Address of the Office / Department :

To

Tagore Public School
Rajapuram

(Name & Address of the Institution)

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

Kmfam
(FRANCIS K. MANI)
PRINCIPAL
Tagore Public School
(Senior Secondary)
(CBSE No: 930382)
P.O. Rajapuram-671532
Kasaragod, Kerala






KERALA WATER AUTHORITY
QUALITY CONTROL SUB DISTRICT LABORATORY KANHANGAD, CHAMUNDIKUNNU
WATER ANALYSIS REPORT

Tele phone No : 04672-266855
email : qualitycontrolsdlkng@gmail.com
qualitycontrolsdlkng@gmail.com

Report No - KWA/QA/R/02/27/J/09/108			Date : 09/02/2024		
Customer Name and Address		1. Date of receipt		:08/02/2024	
The Principal Tagore Public School Rajapuram Rajapuram P.O Kasaragod 671532 (HI TH Poodamkallu Non domestic)		2. Sample Provided by		Customer(QUA_107921)	
		3. Sample Code		09/24(160)	
		4. Source of Sample		Bore well	
		5. Sample quantity		: 1 lit	
		6. Test performing dates		From : 08/02/2024 To :08/02/2024	
Sl.No	Characteristics	Unit	Test Method	Acceptable limits as per IS 10500-2012	Result
1	Colour	CU	IS 3025 (part 04) -2021 (PLATINUM COBALT-VISUAL COMPARISON)	5	
2	Odour		IS 3025 (part 5) -2018	Agreeable	
3	Turbidity	(NTU)	IS 3025 (part 10) -1984 (Reaffirmed 2017)	1	0.04
4	pH @ 25°C		IS 3025 (part 11) -2022	6.5 to 8.5	6.17
5	Total Alkalinity (as CaCO ₃)	(mg/litre)	IS 3025 (part 23) -1986 (INDICATOR METHOD) (Reaffirmed 2019)	200	
6	Total Dissolved Solids (TDS)	(mg/litre)	IS 3025 (part 16) -1984 (Reaffirmed 2017)	500	
7	Total Hardness (as CaCO ₃)	(mg/litre)	IS 3025 (part 21) -2009 (EDTA METHOD) (Reaffirmed 2019)	200	36.00
8	Calcium (as Ca)	(mg/litre)	IS 3025 (part 40) -1991 (EDTA METHOD) (Reaffirmed 2019)	75	
9	Magnesium (as Mg)	(mg/litre)	IS 3025 (part 46) -1994 (Reaffirm+D23:D25ed 2019)	30	
10	Chloride (as Cl)	(mg/litre)	IS 3025 (part 32) -1988 (ARGENTOMETRIC METHOD) (Reaffirmed 2019)	250	6.08

The results stated above related only to the sample(s) submitted for testing. This test certificate shall not be reproduced, except in full without the written approval of the laboratory.

BDL-Below Detection Limit

Analysed By 
Technical Manager
Sahana Nazri

Quality Control Sub District Laboratory, Kanhangad
Kerala Water Authority
Chamundikunnu, Kasaragod - 671532

Authorised By
Quality Manager

* End Of Report*

KWA/QC/SDLKNG/R/17

Issue No: 02

Issue Date : 15.06.2022

Rev No: 001

Rev Date:
15.06.2022

Page 1 of 2





KERALA WATER AUTHORITY
QUALITY CONTROL SUB DISTRICT LABORATORY KANHANGAD, CHAMUNDIKUNNU
WATER ANALYSIS REPORT

Tele phone No : 04672-266855
email : qualitycontrolsdlkng@gmail.com

email : qualitycontrolsdlkng@gmail.com					
Report No - KWA/QA/R/02/27/J/09/108				Date : 09/02/2024	
Customer Name and Address		1. Date of receipt		:08/02/2024	
The Principal Tagore Public School Rajapuram Rajapuram P.O Kasaragod 671532 (HI TH Poodamkallu Non domestic)		2. Sample Provided by		Customer(QUA_107921)	
		3. Sample Code		09/24(160)	
		4. Source of Sample		Bore well	
		5. Sample quantity		: 1 lit	
		6. Test performing dates			
		From : 08/02/2024		To :08/02/2024	
SI No	Characteristics	Unit	Test Method	Acceptable limits as per IS 10500-2012	Result
1	Taste		IS 3025(Part 8)1984(Reaffirmed 2017)	Agreeable	
2	Electrical Conductivity at 25°C	(micro mhos/cm)	IS 3025 (part 14) -2013 (Reaffirmed 2019)		102.9
3	Acidity	(mg/litre)	IS 3025 (part 22) -1986 (Reaffirmed 2019)		
4	Sulphate (asSO ₄)	(mg/litre)	APHA23rd Edition (Turbidimetric method)	200	
5	Fluoride (as F)	(mg/litre)	IS 3025 (part 60) -2008 (Reaffirmed 2013)	1	
6	Iron (as Fe)	(mg/litre)	IS 3025 (part 53) -2003 (Reaffirmed 2014)	1	BDL
7	Nitrate (as NO ₃)	(mg/litre)	APHA23rd Edition (UV Screening method)	45	BDL
8	Residual Chlorine	(mg/litre)	IS 3025 (part 26) -2021	0.2	-

Remarks:

The results stated above related only to the sample(s) submitted for testing. This test certificate shall not be reproduced except in full without the written approval of the laboratory.

BDL-Below Detection Limit

Analysed By

Technical Manager

Sahana Nazri

Quality Manager
Quality Control Sub District Lab, Kanhangad
Kerala Water Authority
Chamundikunnu, Kasaragod - 671532

Authorised By

Quality Manager

* End Of Report*

KWA/QC/SDL/KNG/R/17

Issue No: 03

Issue Date : 25.02.2023

Rev No: 002
Rev Date: 25.02.2023

Page 2 of 2





KERALA WATER AUTHORITY
QUALITY CONTROL SUB DISTRICT LABORATORY KANHANGAD, CHAMUNDIKUNNU
WATER ANALYSIS REPORT

Tele phone No : 04672-266855
email : qualitycotrolsdlkng@gmail.com

Report No - KWA/QA/R/02/44/J/06/53			Date : 09/02/2024		
Tele phone No : 04672-266855			1. Date of receipt : 08/02/2024		
The Principal Tagore Public School Rajapuram Rajapuram P.O Kasaragod 671532 (HI TH Poodamkallu Non domestic)			2. Sample Provided by Customer(QUA_107921)		
			3. Sample Code 09/24(160)		
			4. Source of Sample Bore well		
			5. Sample quantity : 100 ml		
			6. Test performing dates From : 08/02/2024 To : 09/02/2024		
Sl No	Characteristics	Unit	Test Method	Acceptable limits as per IS 10500-2012	Result
1	Total Coliforms	CFU /100 ml	IS 15185:2016; ISO 9308 - 1: 2014	Nil	Nil
2	E.Coli	CFU /100 ml	IS 15185:2016; ISO 9308 - 1: 2014	Nil	Nil

The results stated above related only to the sample(s) submitted for testing. This test certificate shall not be reproduced except in full without the written approval of the laboratory.

Quality Manager
Quality Control Sub District Laboratory
Kerala Water Authority
Chamundikunnu, Kasaragod - 671532

Authorised By
Bacteriologist

* End Of Report*

KWA/QC/SDL/KNG/R/17

Issue No: 02

Issue Date : 15.06.2022

Rev No: 001 Rev Date: 15.06.2022